

## **Cross Sensitivity Data—NH<sub>3</sub> Sensors**

The table below does not claim to be complete. Interfering gases should not be used for calibration. Please [contact us](#) for further support regarding cross sensitivities.

Interfering Gas	Concentration [ppm]	Reading on NH <sub>3</sub> analyzer [ppm]
Cl <sub>2</sub>	20	-55
CO	300	0
CO <sub>2</sub>	20000	0
H <sub>2</sub>	200	0
H <sub>2</sub> S	20	7
NO	20	-1
NO <sub>2</sub>	20	-20
SO <sub>2</sub>	20	-7